

283 N EMPIRE DRIVE
INSPECTION DATA FINALIZED APRIL 2022

PARCEL ID	POINT	PANEL	PRIMARY	TYPE	SIDEWALK DIMENSIONS			[A] EXCESSIVE OR NEGATIVE CROSS SLOPE		[B] EXCESSIVE CRACKING	[C] SPALLING	[D] JOINT/CRACK GAP	[E] OTHER CONDITION		[F] SECTIONS PROJECTS ABOVE WALK		CAUSED BY	CAUSED BY
		STATUS	DEFECT		THICKNESS	LENGTH	WIDTH	PRESENT	EXTENT				PRESENT	DESCRIPTION	PRESENT	EXTENT	UTILITY	TREE
025-002541	1	BAD	[B]	SIDEWALK	4	3	4	NO		YES	NO	NO	YES	vegetation	NO		NO	NO
025-002541	2	BAD	[B]	SIDEWALK	4	5	4	NO		YES	NO	NO	YES	vegetation	NO		NO	NO
025-002541	3	BAD	[B]	APPROACH SIDEWALK	6	6	4	NO		YES	NO	NO	YES	vegetation	NO		NO	NO
025-002541	4	BAD	[F]	APPROACH SIDEWALK	6	5	4	NO		NO	NO	NO	NO		YES	1/2''' - 1'''	NO	NO
025-002541	5	BAD	[F]	APPROACH SIDEWALK	6	5	4	NO		NO	NO	NO	NO		YES	1/2''' - 1'''	NO	NO
025-002541	6	BAD	[E]	SIDEWALK	4	5	4	NO		NO	NO	NO	YES	water box exceeds 1 in (portion in point 7)	NO		YES	NO
025-002541	7	BAD	[E]	SIDEWALK	4	5	4	NO		NO	NO	NO	YES	water box exceeds 1 in (portion in point 6)	NO		YES	NO
025-002541	8	BAD	[A]	SIDEWALK	4	5	4	YES	Negative	NO	NO	NO	NO		NO		NO	NO
025-002541	9	BAD	[A]	SIDEWALK	4	6	4	YES	Negative	NO	NO	NO	NO		NO		NO	NO
025-002541	10	BAD	[A]	SIDEWALK	4	5	4	YES	Negative	NO	NO	NO	NO		YES	1/4''' - 1/2'''	NO	NO
025-002541	11	BAD	[A]	SIDEWALK	4	5	4	YES	Negative	NO	NO	NO	NO		NO		NO	NO
025-002541	12	BAD	[A]	SIDEWALK	4	5	4	YES	Negative	NO	NO	NO	NO		NO		NO	NO
025-002541	13	BAD	[A]	SIDEWALK	4	5	4	YES	Negative	NO	NO	NO	NO		NO		NO	NO
025-002541	14	GOOD		SIDEWALK	4	2	4	NO		NO	NO	NO	NO		NO		NO	NO