

242 EMPIRE DRIVE

PARCEL ID	POINT	PANEL STATUS	PRIMARY DEFECT	TYPE	SIDEWALK DIMENSIONS			[A] EXCESSIVE OR NEGATIVE CROSS SLOPE		[B] EXCESSIVE CRACKING	[C] SPALLING	[D] JOINT/CRACK GAP	[E] OTHER CONDITION		[F] SECTIONS PROJECTS ABOVE WALK		CAUSED BY UTILITY	CAUSED BY TREE
					THICKNESS	LENGTH	WIDTH	PRESENT	EXTENT				PRESENT	DESCRIPTION	PRESENT	EXTENT		
025-002603	1	GOOD		SIDEWALK	4	3	4	NO		NO	NO	NO	NO		NO		NO	NO
025-002603	2	GOOD		SIDEWALK	4	5	4	NO		NO	NO	NO	NO		NO		NO	NO
025-002603	3	GOOD		SIDEWALK	4	5	4	NO		NO	NO	NO	NO		NO		NO	NO
025-002603	4	GOOD		SIDEWALK	4	4	4	NO		NO	NO	NO	NO		NO		NO	NO
025-002603	5	BAD	[A]	SIDEWALK	4	4	4	YES	7.00% +	NO	NO	NO	NO		NO		NO	NO
025-002603	6	BAD	[A]	SIDEWALK	4	5	4	YES	7.00% +	YES	NO	NO	NO		NO		NO	NO
025-002603	7	BAD	[B]	SIDEWALK	4	3	4	NO		YES	NO	NO	NO		YES	1" +	NO	NO
025-002603	8	GOOD		SIDEWALK	4	2	4	NO		NO	NO	NO	NO		NO		NO	NO
025-002603	9	GOOD		SIDEWALK	4	4	4	NO		NO	NO	NO	NO		NO		NO	NO
025-002603	10	GOOD		SIDEWALK	4	4	4	NO		NO	NO	NO	NO		NO		NO	NO
025-002603	11	GOOD		APPROACH SIDEWALK	6	4	4	NO		NO	NO	NO	NO		NO		NO	NO
025-002603	12	GOOD		APPROACH SIDEWALK	6	0	0	NO		NO	NO	NO	NO		NO		NO	NO
025-002603	13	GOOD		APPROACH SIDEWALK	6	4	4	NO		NO	NO	NO	NO		NO		NO	NO
025-002603	14	BAD	[B]	SIDEWALK	4	2	4	NO		YES	NO	NO	NO		NO		NO	NO