Sidewalk Maintenance Program Plan and Specifications

Parcel Information: | Address: 338 HIGHMEADOW CT | Parcel Number: 025-005929



[A] – Excessive cross slope or slopes away from street | [B] – Excessive cracking | [C] – Concrete spalling | [D] – Gaps between joints or cracks | [E] – Other conditions causing an unsafe walking surface | [F] – Sections project above walk

Point Responsibility Primary Defect 4'	' Concrete (sa ft) 6'	' Concrete (sa ft) Joint Re	pair (ft) Patch Aspha	it (sq ft) Patch Concrete (sq ft)
, and a second s	(-1)		Promise (no) a recommendation	(Ed ve) z moon content of (Ed ve)

2	OWNER	[F]	0.00	0.00	4.00	0.00	0.00	
7	OWNER	[B]	20.00	0.00	0.00	0.00	0.00	
-8	OWNER	[B]	20.00	0.00	0.00	0.00	0.00	
9	OWNER	—— [E] [F]	20.00	0.00	0.00	0.00	0.00	
11	OWNER	[E] -	20.00	0.00	0.00	0.00	0.00	Gas valve, replaced* capto be
19	OWNER	[D]	0.00	16.00	0.00	0.00	4.00	cantaha
23	OWNER	[F]	0.00	0.00	4.00	0.00	0.00	10 be
24	OWNER	[F]	0.00	0.00	4.00	0.00	0.00	
37	OWNER	[B]	20.00	0.00	0.00	0.00	0.00	
41	OWNER	[B]	16.00	0.00	0.00	0.00	0.00	
59	OWNER	[B]	20.00	0.00	0.00	0.00	0.00	
60	OWNER	[B]	20.00	0.00	0.00	0.00	0.00	
61	OWNER	[F]	0.00	0.00	4.00	0.00	0.00	
		QUANTITY -	156.00 1 \$ 6.00	16.00	16.00	0.00	4.00	
		COST -	\$2,223.00 \$1,938.	\$236.00	\$272.00	\$0.00	\$58.00	
			A1					

Estimated Owner Cost: \$2,789.00 \$2,504.00

\$1,653.00

\$2,219

* See attached contacts for Columbia Gas, if you choose to do this repair yourself. Cost should be covered by Columbia Gas.

Caitlyn Ridge 2022.08.04 21:12:41 -04'00'

Caittyn Ridge 8/11/22

