

Parcel Information:

Address: 378 DEPAUW CT | Parcel ID: 025-003160



Parcel Summary:

Quantities:

4" Concrete Replacement (SF)	6" Concrete Replacement (SF)	8" Concrete Replacement (SF)	Grinding (LF)	Patch Asphalt (SF)	Patch Concrete (SF)	Vegetation (LF)	ADA Ramp (ea)	Root Pruning (Panel)	Obstructions (ea)
0	0	0	12	0	0	0	0	0	0

Costs:

4" Concrete Replacement Cost	6" Concrete Replacement Cost	8" Concrete Replacement Cost	Grinding Cost	Patch Asphalt Cost	Patch Concrete Cost	Vegetation Cost	ADA Ramp Cost	Root Pruning Cost	Obstruction Cost	Owner Cost	Total Cost
\$1,360.00	\$0.00	\$0.00	\$378.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$6,210.00	\$1,730.00	\$7,918.00
\$ 0.00										\$ 378.00	\$ 6,588.00

Sidewalk Panel Detail

[A] – Excessive cracking | [B] – Concrete spalling | [C] – Gaps between joints or cracks | [D] – Other conditions causing an unsafe walking surface | [E] – Minor Vertical Offset | [F] - Major Vertical Offset (>0.75")

ParcelPanelNumber	Panel Type	Responsibility	Defect	4in Concrete Replacement (SF)	6in Concrete Replacement (SF)	8in Concrete Replacement (SF)	Grinding(LF)	Patch Asphalt (SF)	Patch Concrete (SF)	Vegetation (LF)	Root Pruning (Panel)
5	Sidewalk	Owner	E	0	0	0	4	0	0	0	0
15	Sidewalk	City	D	17	0	0	0	0	0	0	0
16	Sidewalk	City	D	17	0	0	0	0	0	0	0
19	Sidewalk	Owner	E	0	0	0	4	0	0	0	0
25	Sidewalk	Owner	A	17	0	0	0	0	0	0	0
27	Sidewalk	Owner	A	17	0	0	0	0	0	0	0
30	Sidewalk	City	A	17	0	0	0	0	0	0	0
42	Sidewalk	Owner	E	0	0	0	4	0	0	0	0