

Sidewalk Maintenance Program Plan and Specifications



Parcel Information: | Address: **338 HIGHMEADOW CT** | Parcel Number: **025-005929**

[A] – Excessive cross slope or slopes away from street | [B] – Excessive cracking | [C] – Concrete spalling | [D] – Gaps between joints or cracks | [E] – Other conditions causing an unsafe walking surface | [F] – Sections project above walk

Point	Responsibility	Primary Defect	4" Concrete (sq ft)	6" Concrete (sq ft)	Joint Repair (ft)	Patch Asphalt (sq ft)	Patch Concrete (sq ft)
2	OWNER	[F]	0.00	0.00	4.00	0.00	0.00
7	OWNER	[B]	20.00	0.00	0.00	0.00	0.00
8	OWNER	[B]	20.00	0.00	0.00	0.00	0.00
9	OWNER	[E] [F]	20.00	0.00	0.00	0.00	0.00
11	OWNER	[E]	20.00	0.00	0.00	0.00	0.00
19	OWNER	[D]	0.00	16.00	0.00	0.00	4.00
23	OWNER	[F]	0.00	0.00	4.00	0.00	0.00
24	OWNER	[F]	0.00	0.00	4.00	0.00	0.00
37	OWNER	[B]	20.00	0.00	0.00	0.00	0.00
41	OWNER	[B]	16.00	0.00	0.00	0.00	0.00
59	OWNER	[B]	20.00	0.00	0.00	0.00	0.00
60	OWNER	[B]	20.00	0.00	0.00	0.00	0.00
61	OWNER	[F]	0.00	0.00	4.00	0.00	0.00
QUANTITY			156.00	136.00	16.00	0.00	4.00
COST			\$2,223.00	\$1,938.00	\$236.00	\$0.00	\$58.00
Estimated Owner Cost:			\$2,789.00	\$2,504.00			

● Owner Cost ● Caused by tree, Owner cost ● City Cost * Non-prohibited street tree * Prohibited street Tree

