

## Sidewalk Maintenance Program Plan and Specifications



**Parcel Information:** | Address: **336 EMPIRE DR** | Parcel Number: **025-002618**

[A] – Excessive cross slope or slopes away from street | [B] – Excessive cracking | [C] – Concrete spalling | [D] – Gaps between joints or cracks | [E] – Other conditions causing an unsafe walking surface | [F] – Sections project above walk

Point	Responsibility	Primary Defect	4" Concrete (sq ft)	6" Concrete (sq ft)	Joint Repair (ft)	Patch Asphalt (sq ft)	Patch Concrete (sq ft)
3	OWNER	[A]	0.00	24.00	0.00	0.00	0.00
4	OWNER	[A]	20.00	0.00	0.00	0.00	0.00
5	OWNER	[A]	20.00	0.00	0.00	0.00	0.00
6	OWNER	[A]	20.00	0.00	0.00	0.00	0.00
7	OWNER	[A]	20.00	0.00	0.00	0.00	0.00
8	OWNER	[A]	20.00	0.00	0.00	0.00	0.00
9	OWNER	[A]	20.00	0.00	0.00	0.00	0.00
10	OWNER	[A]	20.00	0.00	0.00	0.00	0.00
11	OWNER	[A]	20.00	0.00	0.00	0.00	0.00
12	OWNER	[A]	24.00	0.00	0.00	0.00	0.00
13	OWNER	[A]	24.00	0.00	0.00	0.00	0.00
		<b>QUANTITY</b>	<b>208.00</b>	<b>24.00</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>
		<b>COST</b>	<b>\$2,964.00</b>	<b>\$354.00</b>	<b>\$0.00</b>	<b>\$0.00</b>	<b>\$0.00</b>

**Estimated Owner Cost: \$3,318.00**

● Owner Cost ● Caused by tree, Owner cost ● City Cost \* Non-prohibited street tree \* Prohibited street Tree

